

An Evaluation of the Footpaths in the Stirling **Range National** Park (SRNP)

Pamela Mende

An Evaluation of the Footpaths in SRNP

Issue Research Objectives Study Site Research Methods Results Recommendations Conclusion



 Footpaths in the SRNP are the primary recreation resource – hiking, photography, wildflower viewing

What condition are the footpaths in?

How effective is footpath management?

Research Objectives

Evaluate the footpaths in the SRNP using interval sampling and a modified version of the Trail Problem Assessment Method

 Evaluate the effectiveness of footpath management

 Provide baseline information required for future path management

Study Site





Footpaths in SRNP



Research Methods

Interval Sampling
 Trail Problem Assessment Method (TPAM)

- Footpaths were evaluated from the summit down to the start of the path
 - Ease of measurement
 - Time

Interval Sampling

Measurements taken every 100 metres

Footpath Width
Footpath Slope
Footpath Rockiness

Trail Problem Assessment Method

Soil Texture Erosion Footpath Proliferation Excessive Width Exposed Roots Maintenance Features

- Start and finish points of soil texture and degradation indicators
 Locations of roots and
- maintenance features



Trail Problem Assessment Method

Erosion

- E1= Erosion Depth 5 to 10cm
- E2= Erosion Depth 11 to 15cm
- E3= Erosion Depth 16 to 20cm
- E4= Erosion Depth over 20cm

Footpath Proliferation

Location, number, length of parallel paths

Excessive Width

Start and finish, maximum width

Exposed Roots

Location, depth

Maintenance Features

Condition (1-3)

- 1=Good Condition: very little or no damage, no repairs needed
- 2=Moderate Condition: damaged or worn, repairs are required to improve its condition
- 3 = Poor Condition: extremely damaged or worn, needs urgent replacement

Effectiveness (1-3)

- 1=Very Effective: well designed and placed, very successful at managing the footpath segment.
- 2=Moderately Effective: fairly well designed/placed, moderately successful at managing the footpath segment.
- **3=Ineffective:** poorly designed/placed, unsuccessful at managing the footpath segment.

Results

General Characteristics

- Footpath Degradation
- Footpath Maintenance
- Case Study Mt Trio Vs Talyuberlup

General Characteristics

- Mt Trio
 Length 1658m
 Slope 27.9°
 Rockiness 76.8%
 Width 80cm
- Talyuberlup
 - Length
 - Slope
 - Rockiness
 - Width

- 1473m
- 38.7°
- 59.4%
- **120cm**





Footpath Degradation



Mt Trio and Talyuberlup have similar characteristics and similar visitor numbers, however:

Mt Trio has 0.7% erosion, 4 extra paths

Talyuberlup has 78.1% erosion, 11 extra paths

Why??

Footpath Maintenance

Total Number

Regular Upkeep

Condition

Effectiveness

Footpath Maintenance

 Mt Trio
 725 maintenance features

Regular upkeep

 Talyuberlup
 23 maintenance features

> Informal monitoring once a year

■ % in Good Condition ■ % in Moderate Condition ■ % in Poor Condition



Mt Trio



Bench Bridge Boardwalk Boot Retaining Sand Trap Sign Post Stair (n=0) Water Bar (n=0) Cleaning Wall (n=0) (n=7) (n=0) (n=0) (n=0) (n=15) Station (n=1)



Talyuberlup

Is Current Management Effective?





Mt Trio

Talyuberlup

Short Term Recommendations

- Visitor Data
- Short Term Solutions
- **Mt Trio:**

Talyuberlup:

 Continue with regular upkeep of maintenance features

- Heavy engineering to stabilize path
- Signposting
- Regular upkeep of maintenance features

Long Term Recommendations

Footpath monitoring system

Regular maintenance program

 Increase resources for footpath management

Conclusion

 Footpaths are the primary recreation resource in the Stirling Range National Park

Footpath condition varies greatly

 Sufficient maintenance and regular upkeep can maintain good footpath condition

Footpaths in good condition provide safe and enjoyable experiences for visitors