Alan Clarke's Field Notebooks **CONTINUED**

(INDEX) (UPDATED ON 09 AUG 2014)

(Only pages with notes are numbered)

22. 2002 (05-07-2002/25-11-2002)
23. 2002-2003 (11-11-2002/19-09-2003)
24. 2002-2004 (14-10-03/27-11-03) + (09-03-04/17-06-2004)
25. 2004 (03-08-2004/29-09-2004)
26. 2004-2006 (08-11-2004/19-11-2004) +
(13-03-2006/09-11-2006)
27. 2005-2006 (05-07-2005/10-02-06)
28. 2006-2007 (14-11-2006/07-11-2007)

28A 2008-2009 (25-02-2008/23-02-2009)

29. 2008 (05-03-2008/09-11-2008)
30. 2009 (11-03-2009/04-08-2009)
31. 2009 (18-08-2009/16-11-2009)
32. 2009 (02-12-2009/11-12-2009)
33. 2009-2010 (14-12-2009/19-02-2010)
34. 2010 (26-05-2010/17-09-2010)
35. 2010 (12-10-2010/12-11-2010)
36. 2010-2011 (24-11-2010/28-03-2011)
37. 2011 (07-06-2011/08-06-2011)
38. 2011-2012 (03-11-2011/01-03-2012)
39. 2012 (12-03-2012/27-04-2012)
40. 2012 (07-05-2012/21-08-2012)
41. 2012 (08-09-2012/30-10-2012)
42. 2012 (03-11-2012/07-12-2012)

Alan Clarke's Field Notebooks **CONTINUED**

(INDEX) (UPDATED ON 09 AUG 2014)

(Only pages with notes are numbered)

Alan Clarke's Field Notebooks

(INDEX) (UPDATED ON 09 AUG 2014)

(Only pages with notes are numbered)

1.	1992- 1995	(12-07-1992/19-10-1995)
2.	1995-1996	(06-11-1995/21-11-1996)
3.	1995-1996	(08-11-1995/11-03-1996)
4.	1996	(12-04-1996/29-11-1996)
5.	1996-1997	(09-12-1996/06-08-1997)
6.	1997	(13-08-1997/14-10-1997)
7.	1997-1998	(20-10-97/23-10-1998)
8.	1998	(04-05-1998/04-08-1998)
9.	1998-1999	(08-09-1998/04-02-1999)
9A.	1998	(09-11-1998/24-11-1998) Plus sorting of invertebs. from Muir-Unicup wetlands in 1996 & 1997).
10.	1998-1999	(30-09-1998/18-02-1999)
11.	1999	(15-02-1999/08-06-1999)
12.	1999-2000	(27-05-1999/24-02-2000)
13.	1999-2000	(29-06-1999/20-01-2000)
14.	2000	(29-03-2000/17-04-2000 and 27-09-2000)
15.	2000	(26-04-2000/15-08-2000)
16.	2000-2001	(01-05-2000/16-03-2001)
17.	2001-2002	(30-10-2000-19-07-2001)
18.	2000-2001	(06-11-2000/23-05-2001)
19.	2001	(02-04-2001/08-11-2001)
20.	2001-2002	(26-11-2001/11-04-2002)
21.	2002	(07-05-2002/25-05-2002)


INCLUDES GST
MAY 05 - FEB 06
06100-A6 100 Leaf
9 312136 800432
Made in Indonesia
Collins

(1)

RYAN BUTLER 0429102295
Kalgoorlie

Doris kiss
skinbathing in the rain
&
Dorothy Rose.

(2)

Invert data
water chem data
to Sue for updates.
for Durba Springs and
Lake Disappointment.

+Bill
Stuart - Adrian enter other
projects with the DIWA data
water chem and micro data
assist/add to.
Biological survey work.
SAP. [illegible]
[illegible]

Harris Lake Report to Sue.
Burengoria, Samphire wetland

(3)

✓

Email to Sue waterchem
xcel data for Reports.

~~Yalgoo Reports~~
~~Yuin, Billjilly,~~
~~Narracoony Spring.~~
low priority

46 FELSPAR ST WALSHPOOL
94589711
Malcus Factory
stainless case.

Cameron Hennessy
0428~~01227~~
279230

1943 Km travelled 5/7/05 (4)

depart Greenwood. 0800

met Roger Hearn at Unicup discussed gauge removal on shore with Roger at 9.30 am. Roger rang Tim to discuss. Tim rang me to confirm the removal of Don's 1m gauge, but not to remove 2m gauge with logger attached. 2nd 2m gauge on shore left alone. On site Roger and I removed 1m depth gauge in the middle of the lake and large sign erected by ski club that had fallen over and removed VRC depth monitoring device.

Notes

Mooring (CONT.)

The DLI BM is high on a hill amongst trees + 3m from 2m lake depth and 100m + from usual shore line. The Munro datum is in good cond. and would be suitable to using a level to determine lake depth. The 2m gg with the logger is capable of measuring depths to 0.4 depths below this would be measured using a string line and bubble to 0.3+. These depths are unlikely during normal Dept. NOV needs.

The current 2m gauge with

boyger is likely to be a hazard
if skiing is permitted once
water levels increase
current depth is ≈ 0.8 Boyger
to regain yesterdays depth.
Decision to pursue skiing rights
in management plan process.
tenure skiing in NR to be pursued.
site is being developed as a race site
by the District.
no threat because of low
water levels as 2m gauge
stays in.

Annual Skiing Ranges 1830hrs

(7)

Anderson The 1m gauge was not removed.

(8)

6/7/05

Depart Sterling Ranges 0800

BM 588667

6217157

Anderson 6/7/05

Lake depth 2m shore gg 1.63m.

1m gauge is 0.5m under water gauge identified by a 20mm PVC pipe and float that runs up the pipe with the water level. A screw holds the float in place. Actual gg is 0.55m below current water level.

PVC pipe currently is 0.85 exposed.

WGS 84 E 588911 WPT 333.

N 6217187

34 10 951

117 57.890

6/7/05 (9)

Dumbleyung Lake.

Lake depth at 4m gauge was 2.48m

5m gauge dry 20m upslope

4m gauge submerged. contains 3m plate.

2m gauge 6m gales angle was 10cm underwater and barely visible. Not possible to remove, although attempts were made by attaching ropes and pulling up from the boat. Attached a float with 2m of rope to top of gauge. HAZARD painted twice on the float. Current position 30m from shore just beyond the tree line

Downkeeping
water depth in gauge (2m)
was 2m.



6/7/05

Bennetts

depth pool (1m diameter) around gauge 0.06m dry near gg.
large shallow pool in SE area of lake.
3m gauge behind fringing veg
2m gauge near boat ramp entrance against fringing veg.
1m gauge was removed could be re-installed <45m from shore near southern boundary.
2m gauge is near steep slope to lake bottom possible for string and line to <0.5m.
Use nuts and bolts to secure 2m gg.

Finish at Newdegate Pde
7.15 pm.

Start 0745 7/7/05

Lake depth at 2m gauge on stone
2.04 m. depth plate needs
replacing and "2" stainless plate R.S.
Lake needs a 3m gauge.
BM close to the water, able
to derive levels, although
~~[illegible]~~ are after survey station in
the middle of the lake. 2.05 m water.
2m gauge is at edge of timber
on edge of lake, bar with
1m gauge covered by 1m of water
no driving right on boat ramp

7/7/04

sign is Dept transport. sign had been turned around to face away from view. Warning of no swimming at two places.

Beverley (Quarlandary crossing)
2 of the 3 ggs for Beverley have been removed. The 8m (lowest of 3 ggs) is all that remains. The H_2O is 5cm above the top of the gg. depth plate approx 20cm from surface.
possibly 9m gauge? not 8m. Where check photos of previous Beverley. channel has been excavated. Now has steep sides. It would

be difficult to get a depth reading in this situation.

7/7/04

Very grassy
Shi Lake depth gauge 1.23m
gg 3m from shore at this depth
amongst fringing vegetation
150m away from pickup and
drop off area.
gg 70m north of boat ramp.
did not remove the gauge
because it passes no risk to
divers. This is the only gauge in the
lake.

7/7/05 (16)

Ardath

depth 1.25m

gauge is in 0.30m & water @ 1.25m.
ie 3m from shore inside fringing
& vegetation

gg seems in a safe position and
not a hazard to divers.

water is running past bend
at SW end of lake to ..
the lake is emptying. not likely
to get much deeper.
unlikely that diving occurs.

Spoke with Greg Durell.
Did not retrieve the gg.
Arrive Meredin 1915 hrs.

(17)

Depart Merredin 0800 8/7/05

Campion

depth @ 1m gg 0.53

1m gauge removed and remains of Munro wood board.

The 2m gauge was 2m from the water at 0.53 depth. A string and line could easily be used for depths below 0.8 (ground level for 2m gauge. ~~Lake floor is approx.~~ up to depths approx 0.10m. alternative method required for shallow depths.

iBL at 2m gg is 0.75m

bottom of lake is 10-12m away.

7/7/05

Lake Ninan

depth @ 2nd gg is 1.24m.
1m gauge in 1m of water. A PVC pipe is fixed to the top of the angle and extends up for 1.2m above angle. The PVC pipe has been struck by a boat? and bent over and back straight again. The pipe is not securely fixed now due to damage from impact. I dug around the gauge and tried to remove the gauge, but I was NOT successful. I attached a float and rope to the gauge. The

19

1/7/05

Joan had enough rope to allow a rise in the water level to 3+m. This gauge will need to be removed when H_2O level recedes. The 2m gauge does not pose a hazard ∴ was not removed.

The shire has a sign explaining the Hazards of the lake and that it is/ is not gazetted for skiing and swimmers then upon this at your own risk.

Desmondie falls

Problems

close track off from falls road

above main falls risk management

stop access to slippery rocks.

" " access track to pattern

of foot tracks up slope

Problems

steep slopes retaining walls

track erosion

VRM upper log poles too high

allows children access to falling

Engineer to assess falls bridge

structure (Heritage value)

Viewing deck on top of hill
Seeing vistas changes in slope
etc

Bridge bottle neck. one way
Fences over cliff. Path rock
steps different access old and
unsightly slippery.

Drainage half pipes with grates
steps too high gully
vegetation needs clearing weeds

Boardwalk lifts people above
reeds away from snakes.
Pamphlets, net trunks with info

internet good tool for interpretive information

tracks good to have regular steps → stone stepping gravel.

2nd viewing deck good close to water

steps steeper

opportunities

1st viewing deck near old bridge site on western side so that people can get close to water

consult local community

2ND Deck.

Corral fencing around deck above water under intersp for walking erosion behind deck.

vegetation changes down steps intersp. on deck.

Both of timber steps on track.

erosion on track on both side ongoing maintenance

steps in rock. rock walls hand rails on erosion gullies

maintenance access track
closest at road?

state slope section closest rehab.
divert track to left through
low gradient fire track.

close to bottom of falls
weeping rocks.
track hits rock slope.
signs to direct either through
trees or around against the rock
face.
creeks in creek line. creeks
reduce river to water. remove

weeds, open view, less need
for access trails to creek.
steep banks into creek. path
needs railing.
steep above creek.
address access to the tidal creek.

steep at bend backwater
with fish water source.
unique situation, only important
for 2ND Decks city in view
water use.

steps x 2 Y junction
from track along creek to
lions lookout.

Chappel's chair turn around
to face creek.
investigate lions history
and chappels chair.
picnic table
stops access to river by using
interp about riparian vege.
use locals to plant and rehab
area.

Palm Rd access.
features rock bridge over creek.
design & car park good.
add traffic profiler to stop
loose cats.

Back up on Tap near
main rec facility.
wood bridge over creek
needs 2ND rail for children
full of holes to remove.

Dogs
entry needs to show areas for
Dogs.

Lower RD waterfall walk.
trail bike abuse running
down drainage way.
bollards.

Asherose Dr
Car parks small. not able
to park cars for walking
visitation No?

Henry Road.
Lower slopes provide
Mountain bike access, provide
users for edging, erosion
maintenance etc!

show the analysis
& your concepts.

- inventory
- vision
- concepts.
-

Know your audience

maps.

how can we use this.

we want LD to make recommendations
for materials etc.
detail.

(30)

pH @ Calibration CL 1 metres.

-53.3 mV

-9 mV

(31)

12/9/04

Dobsderry 8.30 am

gauge B 0.51 m.

pH 6.92 @ 12.7°C

gauge B 462985 E.

6437374 N

Benchmark 463070 E

6437226 N.

Track to DOBA 463101

6436926.

Groundspring 10.45

depth 0.69

pH 6.02 @ 14.2°C

(32)

Benchmark 558768 E
6399914 N

(33)

12/9/05

Corrogin 1350
depth gauge A 1·28 m
pH 7·27 @ 16·9°C
Benchmark 603409
6413294

Brown 1444
depth (@ 2m) 1·56 m.
pH 9·40 @ 15·4°C
Benchmark 559598 E
6397741 N

WHITE WATER 1530
depth (1m) 0·20 m
pH 8·68 @ 17·4°C

12/9/05 (34)

Yealering 1600

Benchmark 558592 E
6393388 N

depth @ D(2m) 2.04m.
pH 8.59 @ 14.9°C

DULBINING 1710

depth 0.88m
pH 10.55 @ 16.0°C

WALBYRING 1745

depth (1m) 0.83m.
pH 7.67 @ 14.9°C

35

pH Calibration CE1 method

-52.9 mV

-9 mV

Benchmark 542628 E

6347334 N

36

12/9/05

Franklin North

depth 1.05 from top of angle iron

pH 8.55 @ 15.2°C

13/9/05

Little White @ 815

depth @ 0.72m.

pH 9.68 @ 13.7°C

benchmark 541349 E

6347282 N

White Norrazin 0855

depth offshore 0.06m.

pH 8.25 @ 11.0°C

13/9/05

Tourbin South 10.30
depth 0.33m.
pH 9.93 @ 12.4°C
Benchmark 551257 E
6350393 N

Dumbleyung 11.20
depth (4m) 2.72m
pH 8.15 @ 13.6°C
Float on submerged gauge
missing. Other nav. devises blown
on shore.

13/9/05 (38)

Coomelberrup 12.45

benchmark. 573067 E
6303125 N

depth 1.5m

pH 8.73 @ 14.5°C

~~Coomelberrup~~ 2.00pm
5695 E
Benchmark. 6277308

depth (A)(2m) 1.3m

pH 8.74 @ 15.3°C

Coomelberrup 1500

depth (3m) 2.43m.

pH 7.93 @ 14.6°C

(39)

Brent
0407088991

Benchmark
533154
6307266

13/9/05 (40)

Mortimer 16.20
depth (2m) 1.49m
pH 9.82 @ 14.6°C
Benchmark 516357
6289931

Flagstaff 1650
depth (3m) 1.58m.
pH 8.42 @ 14.2°C
Benchmark 523636
6291472

Portlayering 1800
depth 1.5m
pH 8.28 @ 14.2°C

(41)

pH Calibration CE1 method

-52.8 mV

-10 mV

(42)

14/9/05

West Anchor 0815

benchmark 4965810

6293014

depth (approx 2m) 1.01 m.

pH 8.92 @ 13.8°C

Tauriemma 0900

benchmark 480703

6283951

depth 1385mm from top of hand rail post on jetty to water 9TH post from shore.

pH 8.48 @ 13.4°C

14/9/05

Kulhulyp
depth 0.54m.
pH 7.23 @13.5°C
benchmark 469769
6257314

Egret 1315
depth 0.4m
pH 6.05 @14.7°C
benchmark 379665 E
6314852 N
Night Herons nesting 2+ pairs
possibly more.

14/9/05

Harvey 1420
depth 1.19 m.
pH 5.28 @ 17.3°C
Benchmark 386573
6348941

Nine Mile 1515
depth 0.8 m.
pH 6.59 @ 18.7°C
Benchmark 385555
6376520

14/9/05

Mclarty 1620
Benchmark 3794 15
6379682
depth (onshore) 1.27m.
pH 7.56 @ 17.3°C

Clifton L
depth (5) 4.36m
pH 8.39 18.1°C
Benchmark 374037
6376134

(46)

pH Calibration CL1 method

-53.5 mV

-7 mV

(47)

15/9/05

THOMPSONS 0845

Benchmark. 389510

6441479

depth 0.98 m. gg (A)

pH 7.16 @ 15.9°C

GIBB ROAD 10.00 am

depth (WR) 24.83

pH 6.35 @ 15.0°C

Benchmark 397541

6441798

(48)

15/9/05

Forrestdale 10·45

depth 22·29 m AHD

pH 10·41 @ 17·2°C

Benchmark 400102E

6442247N

Jandakot 1330

depth (WRC)[1] 44·92 m AHD.

pH 6·23 @ 19·1°C.

Benchmark 390957

6486980

(49)

15/9/05

Joondalup 1430

depth 16.98 m.

pH 9.35 @ 19.5°c

Benchmark 384371

6487424

Calibration WTW 320

Auto Cal TEC

-51.6mV

-8mV

pH 10.22 @ 17.5°C

Depart Greenwood

7/11/05 0715 hrs.

7/11/05

Beverley 10.00am.

720mm from road surface to water on up stream side.

10m (WRC) - 720mm = 9.28m.

↑

2 gauges in water ∴

low gauge Top 8m

high gauge Top 9m.

pH 9.53 @ 20.7°C

(52)

7/11/05

Meero 11.00am.

depth g 0.82m. (1mg)

pH 9.95 @ 23.0°C taken

1m depth plate ~~missing~~, needs replacing.

Convergin 1.00pm

gauge A 603379 E WGS 84

6413203 N

gauge B 603368 E

6413094 N

depth 1.18m.

pH 7.68 @ 22.0°C

NO FILTERED

7/11/05 (53)

Brown 2.30pm
gauge 2m on shore 1.37m.
pH 10.23 @ 24.2°C

White Water 2.50pm.
dry at 1m gauge
filled & water on opposite
side of lake <0.010m deep.

Yealering 3.15pm.
gauge (2m) 1.84m.
2m plate needs replacing
damaged by falling tree.
pH 9.96 @ 23.4°C

7/11/05 (54)

Dallimmering 4.15pm.
depth 0.71m.
pH 10.12 @ 25.0°C

NOT FILTERED
Wellspring 5.00pm.
depth 6.69m
pH 7.95 @ 21.5°C.

Taarblin North 5.45pm
1190mm from Top of gate to water.
pH 7.77 @ 21.2°C

finish Narrogin 6.45pm

55

Calibration WTW 320

Auto Cal TEC

-51.5 mV

-11 mV

56

8/11/05

Little White 8.00 am

depth 0.56 m.

pH 9.37 @ 16.1°C

White (Norwegian)

dry.

Tourbelin 9.00 am.

depth 0.13 m.

pH 8.94 @ 15.1°C

8/11/05 (57)

Dumbleyung 10.30am
gauge B (4m) depth 2.60m.
pH 8.40 @ 17.2°C
2 x loops still attached to 2m
depth gauge

Cornelldamup 11.45am
depth 1.32m. (mud)
worm egg and other eggs
along wash line 0.5m above water
wash line is thick/large.
pH 9.40 @ 18.9°C

8/11/05 (58)

Lazzarina 1.00pm.
depth (2nd) 0.97m.
pH 10.48 @ 19.2°C
both depth plates need replacing.

Cogreenup 2.15pm
depth 2.25m.
pH 8.50 @ 20.2°C.
water flowing out of lake at western culvert.

Martinup 4.00pm.
depth (2nd) 1.37m.
pH 10.55 @ 18.9°C

(59)

Calibration WTW 320

-51.3 mV

-9 mV

START 7.00 am.

(60)

8/11/05

Aggrstaff 4.20

depth (3m) 1.45m.

pH 9.29 @ 20.6°C

Portsegerring 5.30 pm.

depth 1.35 m.

pH 9.68 @ 19.2°C.

finish Wagin - 6.15 pm.

West Arthur River 9/11/05

depth on shore (2m) 0.86 m.

pH 10.28 @ 15.9°C.

8.00 am.

9th post 1470 = 2.2m NOV

9th post 1385 = SEPT

95mm

2.2 SEPT

95 2.295m

9/11/05

Towerrimming 9.00am.

depth 2.2m.

depth gauge on 7th pillon in good cond., best 200mm under water need a 3m plate on opposite side of jetty on 9th pillon.

pH 8.90 @ 17.9°c

not filtered

Kuhcrap Bayup Brook.

depth 0.56m. 10.00am.

pH 7.32 @ 18.3°c

9/11/05

Egret Swamp.
depth 0.24m. 1.00pm.
pH 5.92 @ 18.1°C.

Harvey 2.15pm.
depth 1.34m.
pH 5.54 @ 22.5°C.

Nine Mile 3.20pm
depth 0.85m.
pH 6.57 @ 21.8°C

McLarty 4.00pm.
depth on shore (2m) 1.22m.
pH 8.29 @ 23.2°C

Calibration WTW320
-50.8mV
-9mV

9/11/05

Clifton 5.00pm.
depth 4.30m.
pH 8.74@22.7°C

Ignite 6.30pm Greenmount.

Forrestdale 10/11/05
1000hrs
depth 22.33m AHD.
pH 10.45@21.3°C.

Gibb Road 11.15am.
depth 24.56m AHD.
pH 6.47@19.1°C

10/11/05

Thomsons lake

depth 0.94m. (A)

pH 6.72 @ 19.0°C

depth gauge A loose in ground. needs replacing further into lake.

Typha needs cutting back so that gauge C (2m) can be found.

(67)

BOOH NOV 2005

COMPST 04

start 0630 15/11/05 (68)

CAMP BAY

north lake/Comp bay
Darter 2+1
with Black Cormorant 4

OSC-01
CAMPSTOH GPS not consistent
depth 1.2m
salinity sample
max depth @ lake 1.7m.
pH Calibration OK. -50.6 mV
pH 8.34 @ 21.3°C -7mV

re 05

spotted using binoculars.
graceful up (swoopes) down flight, clear black
head gull. watched gull
drop vertically to the water
near a group of silver gulls
roosting in a dead tree.
The gull was low in the water.
slender looking compared with SG
wings and back darker grey
than SG. tail feathers barred
black and white. Bill reddish
brown thinner and shorter than
SG. Head almost black,
lighter near Bill, Black line from
under chin to back of head.
observed for some time.

15/11/05

05C-02 Central Pool. pm.
70+ Pelican
Silver gulls 100
LBC 8+7
Shelduck. 30 + 10 + 10
Hooded Gull, Franklins
Little Pied Cormorant 2
pH 8.18 @ 24.7°C
water sample taken
1 Km south 630622 E
05C-03 6554618 N

16/11/05 (71)

Start 0600

Southern lake.

walked out onto peninsular

Top north end LBC 4 + 2

feeding → shelduck 4 +20 +175 +200 +200 +400

Great egret. 3

~~Grey Teal~~. Black Duck ×2

Pelican 20 Darter 1

05C04 silver gull ×6 displaying

SOUTHLAND97 depth 3.3m

other depths 2.5, 2.9, 3.4 beach area

water sample taken.

pH 8.35 @ 35.4°c

Bottom end 300 shelduck.

16/11/05 (73)

05C-05

investigate fresh water seeps on Western shore
500 ml water sample taken
moved across lake
depths taken. 05C-06

pH Boundary Seeps
6.93 @ 24.1°C.

finish 1800.

pH Calibration Auto CAL TEC
7-10 pts.
-52.9 mV
-8 mV
Calibration OK.

17/1/06

Depart Woodvale 0900
Beverley 17.00 re fuel Brookton get LUNCH

water lying in paddocks and on road edges. Avon River, full and flowing strongly
water level measured from 10m mark on Quelandary crossing.
Crossing has overflowed recently water flowing strongly through partially open gates
Salinity Catchment Group measure water sample as 53 ms/cm.
pH 7.81 @ 25-3°C

Corrosion area
sheet flow
water on road sides
washed over creeks
sand and debris over road
entering Corrosion

Calibration 7-4 ph.
-58.1 mV
-7 mV
Calibration O.K.

17/1/06

Mears 1.20 pm.
depth 2.76 m
water level 10 cm below peak
flood/wash line.
current water level 1m below JAN 2000.
pH 7.12 @ 30.6°C.

Ardath 3.45 pm.
depth 1.28 m.
pH 4.34 @ 29.9°C

Red Lake 4.15 pm.
depth 0.14 m.
pH 4.13 @ 34.6°C

17/1/06

Corrogin 5.30 pm.

depth (A) 1.75m.

pH 6.81 @ 31.9°C

Calibration 7.10

-53.4 mV

-8 mV

finish Corrogin 1830

start ~~0700~~ 0645.

Calibration 7.10 ph

-52.9 mV

-9 mV

Yealering String Line + level
BM = 2.705
BM to water level 0.28
depth = 2.42 m

18/1/06

Brown 7.45
lake has receded 400mm from
main Jetty.
depth (A)(2m) 2.12 m
pH 6.71 @ 25.0°C
explanation & amphipods
water drawn.

WHITE WATER 0800
pH 6.74 @ 26.2°C
depth 1.85 m

Yealering 8.45am
depth 2.42 m.
pH 7.51 @ 27.3°C

18/1/06

Dulbrinning 9.45am

depth 1.24m

pH 6.90 @ 26.3°C.

water has overflowed from Dulbrinning across the road to Toolibin. Currently flowing strongly into Toolibin NR.

Toolibin 10.30am

depth (1)(B) 0.96m.

pH 6.81 @ 27.0°C

lake appears to be silty ie. no higher wash line.

18/1/06

Wallegoring 11.00
depth 1.15m.
pH 6.91 @ 26.6°C
water flowing through culverts into Wallegoring NR: Not sure if this water is entering the lake ~~water~~ Lake has no recent high flood line.

Tarcutta North 11.40
depth 480mm from top of dropper to water
pH. 7.68 @ 28.4°C
dropper 10m from track edge on left facing lake.

18/1/06

WHITE (Narrogin) 1215
depth 0.09m.
pH 8.70 @ 30.1°c
Lorine shrimp present in lake.
water clear.

Little White 1300
depth 0.63m.
pH 8.00 @ 28.9°c.

Tacarblin 1.45pm.
depth 0.13m.
pH 8.53 @ 32.7°c

18/1/06 (83)

Coomelberrup 3.15 pm.
depth 1.47 m.
pH 8.14 @ 28.8°c
2000 Tan yeast line 1m above current height.

Dumbleyung 4.45
depth 2.38 m.
pH 8.73 @ 23.6°c

finish Wagin 1900 hrs.

Calibration 7-10
-52.4 mV
-9 mV

19/1/06

depart Wagin 0630
Katanning refuel, buy lunch.

Longreach 0800
depth ② 1.91 m.
lots of swans coot + other ducks.
pH 9.50 @ 21.5°C.

Carnarvina 8.45
depth 0.64 m.
pH 8.58 @ 20.9°C.

19/1/06

Altham 10.30
depth 0.44 m.
pH 8.88 @ 23.2°C.
masses of Brine shrimp.

Yadup 1145
depth 1.48 m.
pH 7.65 @ 26.6°C

Ranger Road 12.30
depth 1.87 m.
pH 6.53 @ 23.5°C.

87

19/1/06

Brayde

depth 2.30pm.

pH 6.42 @ 26.2°C water

East lake Brayde

depth 19cm from top

& SSM demand plate to

water.

down

pH 6.27 @ 27.3°C



Yakoop
Alcoa & Southern Hwy
through Marbona → Hamel
Waggrup.
Control point
left Control point
widow Dale Road

89

6/2/06

Workcode 8.30 am
depart 12.30 to Magenta

unpack vehicle and setup
house finish 7.30 pm.

wake up 0550 7/2/06
~~depart~~ organise field gear
8.30-7.00
depart for 1st grid 0715

1.5 grids completed

finish on house 1800 hrs.
~~0900~~

90

7/2/06

up 0550 hrs

depart house 0700

finish 1800 hrs.

THURSDAY 8/2/06

up 0550 hrs

leave house 0700 hrs

finish grid on Magenta

moving tea on House

Drive to Dunn Rock.

do one grid

back on house 5.50

finish 1830.

9/2/06 (92)

up 0545
depart house 0645

finish at house 1900.

SUNDAY 10/2/06

depart house 0730

finish last grid at Dunn Rock.

lunch at House 2:00 pm.

clean and organise house

finish at 1700 hrs.

6mm 10
3mm 15
10mm 4
} 29 gauges.

gale angle 5
3×6=18
} 23

5mm double ended drill bits.