SK MANAGEMENT SECTION



Nature of Incident: Injury □ Property Damage ☒

Date: 07/02	2/2011			Alert No: 16
Source: In	nternal⊠	External		
Author: RN	MS			
Identified I Risk Ratin	Hazard: Modified g: Low [I Fuel Containers Moderate □	High∐	Significant ⊠

Other: Description of Incident:

> Heavy Duty truck was on a fire line adjacent to running fire. Fuel Vapors arising from a modified unleaded chainsaw fuel container "exploded" in chainsaw storage cabinet. This resulted in cabinet door hinges being damaged and storage cabinet door opening at speed. Flames were observed exiting the cabinet for a short period immediately following the "explosion". Many small embers and tree bark were present at the time of occurrence with staff removing many small glowing "fire brands" from the truck.

Near-hit

Incident Time and Date:

December 2010

Equipment Involved:

Modified Fuel Container

Recommendations:

- ALL modified fuel containers are to be removed immediately out of service, by Informing all employees of issue and have all trucks inspected to ensure compliance
- **DO NOT** Modify fuel containers

Example of a modified fuel container

